




## Elektrikli Ceraskal



Model	Çalışma Yüğü	Kaldırma Hızı	Döngü	Yük Zinciri	Zincir Donamı	Mak Kaldırma Yüksekliği	Güç Çıkışı	Ağırlık
FAH05/500	500	7	40	6,3 x 19,1	1	30	0,9	43
FAH10/1000	1.000	7,6	40	7,1 x 21,2	1	30	1,6	56
FAH20/2000	2.000	3,8	40	7,1 x 21,2	2	15	1,6	64
FAH30/3000	3.000	2,5	40	7,1 x 21,2	3	10	1,6	83